

cost approximately \$511 per helicopter. Based on these figures, the total cost impact of the proposed AD on U.S. operators is estimated to be \$121,635.

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

#### The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

##### § 39.13 [Amended]

2. Section 39.13 is amended by removing Amendment 39-10421 (63 FR 14026, March 24, 1998 and 63 FR 38742, July 20, 1998), and by adding a new airworthiness directive (AD), to read as follows:

**Bell Helicopter Textron, Inc. and Agusta S.p.A.:** Docket No. 99-SW-27-AD. Supersedes AD 98-07-03, Amendment 39-10421, Docket No. 97-SW-58-AD.

**Applicability:** Bell Helicopter Textron, Inc. Model 412, 412CF, and 412EP helicopters and Agusta S.p.A. Model AB412 helicopters, with tail rotor yoke assembly, part number (P/N) 212-011-702—all dash numbers, installed, certificated in any category.

**Note 1:** This AD applies to each helicopter identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For helicopters that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (e) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

**Compliance:** Required as indicated, unless accomplished previously.

To prevent static and dynamic overload damage to the tail rotor yoke (yoke) that could result in loss of the tail rotor and subsequent loss of control of the helicopter, accomplish the following:

(a) Before further flight, review the historical records of the yoke assembly for any static or dynamic overload damage history, other than normal usage, that could have imposed a bending load on the yoke but did not require replacing the yoke assembly; for example, an incident in which a damaged tail rotor blade was replaced due to a blade strike. If such a history exists, replace the yoke with an airworthy yoke.

(b) Before further flight, unless the requirements of paragraph (c) of this AD have been accomplished previously:

(1) Install a Never Exceed Velocity (Vne) red line at 120 knots indicated airspeed (KIAS) on the pilot and copilot airspeed indicators using red tape or paint and a slippage indicator on the instrument case and glass.

(2) Install a placard made of material that is not easily erased, disfigured, or obscured on the instrument panel in clear view of the pilot and copilot: "Observe temporary Maximum Never Exceed (Vne) airspeed red line (marked at 120 knots indicated airspeed (KIAS)). Vne is 20 KIAS less than the value presented on the airspeed limitation placard for each ambient condition."

(3) Insert the applicable Bell Helicopter Textron (BHT) 412 Temporary Revision, dated August 16, 1996, into the Model 412 Rotorcraft Flight Manual (RFM) or the applicable section of Agusta AB412 Temporary Revision No. 2, dated April 17, 1997, into the Model AB412 RFM.

(c) Within 180 calendar days:

(1) Remove yoke assembly, P/N 212-011-702—all dash numbers, and replace it with an airworthy yoke assembly, P/N 212-011-702—all dash numbers, with zero hours time-in-service (TIS), or an airworthy yoke (regardless of TIS) that has passed a one-time x-ray diffraction inspection in accordance with BHT Alert Service Bulletin (ASB) 412-96-89, Revision A, dated October 17, 1997; BHT ASB 412CF-96-01, dated September 3, 1996; or, Agusta Bolletino Tecnico (Technical Bulletin) No. 412-65, dated April 17, 1997, whichever is applicable.

(2) Install an airworthy tail rotor flapping stop, P/N 212-011-713-103.

(3) After the requirements of paragraphs (c)(1) and (c)(2) of this AD are accomplished,

remove the 120 KIAS redline from the pilot and copilot airspeed indicators; remove the Vne airspeed restriction placard; and remove the BHT 412 Temporary Revision, dated August 16, 1996; BHT ASB 412CF-96-01, dated September 3, 1996; or Agusta AB412 Temporary Revision No. 2, as applicable, from the RFM.

(d) After accomplishing the requirements of paragraph (c) of this AD, at intervals not to exceed 25 hours TIS, inspect the yoke assembly and tail rotor flapping stop (stop) in accordance with Part III, Recurring 25-Hour Special Inspection and Conditional Inspection Requirement, of Bell Helicopter Textron ASB 412-96-89, Revision A, dated October 17, 1997; BHT ASB 412CF-96-01, dated September 3, 1996; or Agusta Bolletino Tecnico (Technical Bulletin) No. 412-65, dated April 17, 1997, as applicable. Replace any unairworthy yoke assembly or stop with an airworthy yoke assembly or stop before further flight.

(e) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Regulations Group, Rotorcraft Directorate, FAA. Operators shall submit their requests through an FAA Principal Maintenance Inspector, who may concur or comment and then send it to the Manager, Regulations Group.

**Note 2:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Regulations Group.

(f) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the helicopter at airspeeds not to exceed 120 KIAS to a location where the requirements of this AD can be accomplished.

**Note 3:** The subject of this AD is addressed in Registro Aeronautico Italiano (Italy) AD 97-223, dated August 1, 1997.

Issued in Fort Worth, Texas, on January 8, 2001.

**Henry A. Armstrong,**  
Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 01-1587 Filed 1-19-01; 8:45 am]

**BILLING CODE 4910-13-U**

#### DEPARTMENT OF TRANSPORTATION

#### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 2000-NM-272-AD]

RIN 2120-AA64

#### Airworthiness Directives; Bombardier Model DHC-7 Series Airplanes

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This document proposes the adoption of a new airworthiness

directive (AD) that is applicable to certain Bombardier Model DHC-7 series airplanes. This proposal would require modification of the pressure hoses to the ground spoiler actuators. This proposal is prompted by issuance of mandatory continuing airworthiness information by a foreign airworthiness authority. This action is necessary to prevent blockage of pressure hoses to the ground spoiler actuators, leading to uncommanded deployment of the ground spoilers, resulting in reduced controllability of the airplane. This action is intended to address the identified unsafe condition.

**DATES:** Comments must be received by February 21, 2001.

**ADDRESSES:** Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2000-NM-272-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: 9-anm-nprmcomment@faa.gov. Comments sent via fax or the Internet must contain "Docket No. 2000-NM-272-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 for Windows or ASCII text.

The service information referenced in the proposed rule may be obtained from Bombardier, Inc., Bombardier Regional Aircraft Division, 123 Garratt Boulevard, Downsview, Ontario M3K 1Y5, Canada. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, New York Aircraft Certification Office (ACO), 10 Fifth Street, Third Floor, Valley Stream, New York.

**FOR FURTHER INFORMATION CONTACT:** Ezra Sasson, Aerospace Engineer, ANE-172, FAA, New York ACO, 10 Fifth Street, Third Floor, Valley Stream, New York 11581; telephone (516) 256-7250; fax (516) 568-2716.

#### **SUPPLEMENTARY INFORMATION:**

##### **Comments Invited**

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications

received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this action may be changed in light of the comments received.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.
- For each issue, state what specific change to the proposed AD is being requested.
- Include justification (*e.g.*, reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this action must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2000-NM-272-AD." The postcard will be date stamped and returned to the commenter.

##### **Availability of NPRMs**

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2000-NM-272-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

##### **Discussion**

Transport Canada Civil Aviation (TCCA), which is the airworthiness authority for Canada, notified the FAA that an unsafe condition may exist on certain Bombardier Model DHC-7 series airplanes. TCCA advises that an operator has reported that an uncommanded deployment of all ground spoilers occurred during an engine ground-run and that all attempts by the flight crew to retract the spoilers were unsuccessful. Investigation of the problem identified the cause as a failed piston seal in a pressure hose to the ground spoiler actuators. This condition, if not corrected, could result in the blockage of pressure hoses to the ground spoiler actuators, leading to uncommanded deployment of the

ground spoilers, resulting in reduced controllability of the airplane.

##### **Explanation of Relevant Service Information**

Bombardier has issued Service Bulletin 7-27-90, dated September 3, 1999, which describes procedures for modification of the pressure hoses to the ground spoiler actuators. Accomplishment of the actions specified in the service bulletin is intended to adequately address the identified unsafe condition. TCCA classified this service bulletin as mandatory and issued Canadian airworthiness directive CF-99-29, dated November 3, 1999, in order to assure the continued airworthiness of these airplanes in Canada.

##### **FAA's Conclusions**

These airplane models are manufactured in Canada and are type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, TCCA has kept the FAA informed of the situation described above. The FAA has examined the findings of TCCA, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

##### **Explanation of Requirements of Proposed Rule**

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design registered in the United States, the proposed AD would require accomplishment of the actions specified in the service bulletin described previously.

##### **Cost Impact**

The FAA estimates that 30 airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 4 work hours per airplane to accomplish the proposed modification, and that the average labor rate is \$60 per work hour. There would be no charge for required parts. Based on these figures, the cost impact of the proposed AD on U.S. operators is estimated to be \$7,200, or \$240 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would

accomplish those actions in the future if this proposed AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

### Regulatory Impact

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

### The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

**Bombardier, Inc. (Formerly de Havilland, Inc):** Docket 2000–NM–272–AD.

**Applicability:** Model DHC–7 series airplanes, serial numbers 003 through 113 inclusive; certificated in any category.

**Note 1:** This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

**Compliance:** Required as indicated, unless accomplished previously.

To prevent blockage of pressure hoses to the ground spoiler actuators, leading to uncommanded deployment of the ground spoilers, resulting in reduced controllability of the airplane, accomplish the following:

#### Modification

(a) Within 12 months after the effective date of this AD: Modify the pressure hoses on each ground spoiler actuator, in accordance with Bombardier Service Bulletin 7–27–90, dated September 3, 1999.

#### Alternative Methods of Compliance

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, New York Aircraft Certification Office (ACO). Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, New York ACO.

**Note 2:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the New York ACO.

#### Special Flight Permits

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

**Note 3:** The subject of this AD is addressed in Canadian airworthiness directive CF–99–29, dated November 3, 1999.

Issued in Renton, Washington, on January 11, 2001.

**Donald L. Riggin,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*  
[FR Doc. 01–1663 Filed 1–19–01; 8:45 am]

**BILLING CODE 4910–13–U**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 2000–NM–263–AD]

RIN 2120–AA64

#### Airworthiness Directives; Construcciones Aeronauticas, S.A. (CASA), Model CN–235 Series Airplanes

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This document proposes the adoption of a new airworthiness directive (AD) that is applicable to all CASA Model CN–235 series airplanes. This proposal would require installing a second electrical connector in the electrical Master Central Unit. This action is necessary to prevent the loss of electrical power, other than that provided by the emergency system, in the event of disconnection of the single electrical connector within the electrical Master Central Unit. This action is intended to address the identified unsafe condition.

**DATES:** Comments must be received by February 21, 2001.

**ADDRESSES:** Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM–114, Attention: Rules Docket No. 2000–NM–263–AD, 1601 Lind Avenue, SW., Renton, Washington 98055–4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227–1232. Comments may also be sent via the Internet using the following address: 9-anm-nprmcomment@faa.gov. Comments sent via fax or the Internet must contain "Docket No. 2000–NM–263–AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 for Windows or ASCII text.

The service information referenced in the proposed rule may be obtained from Construcciones Aeronauticas, S.A., Getafe, Madrid, Spain. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

**FOR FURTHER INFORMATION CONTACT:** Dan Rodina, Aerospace Engineer, ANM–116, FAA, 1601 Lind Avenue, SW., Renton,