

Alternative Methods of Compliance

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

Special Flight Permits

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(d) The actions shall be done in accordance with Boeing Service Bulletin 2411, Revision 2, dated April 29, 1968. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Effective Date

(e) This amendment becomes effective on March 11, 2002.

Issued in Renton, Washington, on January 25, 2002.

Ali Bahrami,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. 02-2319 Filed 2-1-02; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. 2001-CE-03-AD; Amendment 39-12629; AD 2002-02-01]

RIN 2120-AA64

Airworthiness Directives; Eagle Aircraft Pty. Ltd. Model 150B Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that applies to certain Eagle Aircraft Pty. Ltd. (Eagle) Model 150B airplanes. This AD requires you to modify the attachment of the port and starboard throttle arms, and the starboard bushing of the throttle torque tube. This AD is the result of mandatory continuing airworthiness information (MCAI) issued by the airworthiness authority for Australia. The actions specified by this AD are intended to prevent failure of the throttle control assembly caused by rivets of the wrong size. Such failure could lead to reduced control of the airplane.

DATES: This AD becomes effective on March 21, 2002.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in the regulations as of March 21, 2002.

ADDRESSES: You may get the service information referenced in this AD from Eagle Aircraft Pty. Ltd., Lot 700 Cockburn Road, Henderson WA 6166 Australia; telephone: (08) 9410 1077; facsimile: (08) 9410 2430. You may view this information at the Federal Aviation Administration (FAA), Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 2001-CE-03-AD, 901 Locust, Room 506, Kansas City, Missouri 64106; or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT:

Fredrick A. Guerin, Aerospace Engineer, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712; telephone: (562) 627-5232; facsimile: (562) 627-5210.

SUPPLEMENTARY INFORMATION:**Discussion***What Events Have Caused This AD?*

The Civil Aviation Safety Authority (CASA), which is the airworthiness authority for Australia, notified FAA that an unsafe condition may exist on certain Eagle Model 150B airplanes. The CASA reports that Eagle manufactured certain Model 150B airplanes with rivets of the wrong size on the throttle control assembly. Installed rivets that are not the right size have resulted in reduced structural integrity of the throttle control assembly.

What Is the Potential Impact if FAA Took no Action?

If this condition is not corrected, failure of the throttle control assembly could result. Such failure could lead to reduced control of the airplane.

Has FAA Taken any Action to This Point?

We issued a proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an AD that would apply to certain Eagle Model 150B airplanes. This proposal was published in the **Federal Register** as a notice of proposed rulemaking (NPRM) on November 5, 2001 (66 FR 55894). The NPRM proposed to require you to replace existing 3/32-inch rivets, which attach the throttle torque tubes to the port and starboard throttle arms, with 1/8-inch solid-head rivets; and replace the 1/8-inch rivet in the starboard bushing of the throttle torque tube with a 5/32-inch screw.

Was the Public Invited To Comment?

The FAA encouraged interested persons to participate in the making of this amendment. We did not receive any comments on the proposed rule or on our determination of the cost to the public.

FAA's Determination*What Is FAA's Final Determination on This Issue?*

After careful review of all available information related to the subject presented above, we have determined that air safety and the public interest require the adoption of the rule as proposed except for minor editorial corrections. We have determined that these minor corrections:

- Provide the intent that was proposed in the NPRM for correcting the unsafe condition; and
- do not add any additional burden upon the public than was already proposed in the NPRM.

Cost Impact*How Many Airplanes Does This AD Impact?*

We estimate that this AD affects 5 airplanes in the U.S. registry.

What Is the Cost Impact of This AD on Owners/Operators of the Affected Airplanes?

We estimate the following costs to accomplish the modification:

Labor cost	Parts cost	Total cost per airplane	Total Cost on U.S. operators
2 workhours × \$60 = \$120	\$50	\$170	\$170 × 5 = \$850.

Regulatory Impact

Does This AD Impact Various Entities?

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

Does This AD Involve a Significant Rule or Regulatory Action?

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a

substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the final evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Actions	Compliance	Procedures
Replace the existing $\frac{3}{32}$ -inch rivets, which attach the throttle torque tubes to the port and starboard throttle arms, with $\frac{1}{8}$ -inch solid-head rivets, and replace the $\frac{1}{8}$ -inch rivet in the starboard bushing of the throttle torque tube with a $\frac{5}{32}$ -inch screw.	Within the next 100 hours time-in service (TIS) after March 21, 2002 (the effective date of this AD).	In accordance with Eagle Service Bulletin 1067, Revision 1, dated October 21, 1999.

(e) *Can I comply with this AD in any other way?* You may use an alternative method of compliance or adjust the compliance time if:

- (1) Your alternative method of compliance provides an equivalent level of safety; and
- (2) The Manager, Los Angeles Aircraft Certification Office (ACO), approves your alternative. Submit your request through an FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Los Angeles ACO.

Note 1: This AD applies to each airplane identified in paragraph (a) of this AD, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (e) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if you have not eliminated the unsafe condition, specific actions you propose to address it.

(f) *Where can I get information about any already-approved alternative methods of*

compliance? Contact Fredrick A. Guerin, Aerospace Engineer, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712; telephone: (562) 627-5232; facsimile: (562) 627-5210.

(g) *What if I need to fly the airplane to another location to comply with this AD?* The FAA can issue a special flight permit under sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate your airplane to a location where you can accomplish the requirements of this AD.

(h) *Are any service bulletins incorporated into this AD by reference?* Actions required by this AD must be done in accordance with Eagle Service Bulletin 1067, Revision 1, dated October 21, 1999. The Director of the Federal Register approved this incorporation by reference under 5 U.S.C. 552(a) and 1 CFR part 51. You can get copies Eagle Aircraft Pty. Ltd., Lot 700 Cockburn Road, Henderson WA 6166 Australia. You can look at copies at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri, or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. FAA amends § 39.13 by adding a new AD to read as follows:

2002-02-01 Eagle Aircraft PTY. Ltd.:

Amendment 39-12629; Docket No. 2001-CE-03-AD.

(a) *What airplanes are affected by this AD?* This AD affects Model 150B airplanes, serial numbers 001 through 021, that are certificated in any category.

(b) *Who must comply with this AD?* Anyone who wishes to operate any of the airplanes identified in paragraph (a) of this AD must comply with this AD.

(c) *What problem does this AD address?* The actions specified by this AD are intended to prevent failure of the throttle control assembly. Such failure could lead to reduced control of the airplane.

(d) *What actions must I accomplish to address this problem?* To address this problem, you must accomplish the following:

Note 2: The subject of this AD is addressed in Australian AD Number X-TS/4, effective July 6, 2000.

(i) *When does this amendment become effective?* This amendment becomes effective on March 21, 2002.

Issued in Kansas City, Missouri, on January 24, 2002.

Michael K. Dahl,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 02-2318 Filed 2-1-02; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Airspace Docket No. 01-AWP-22]

Revision to Class E Surface Area at Marysville Yuba County Airport, CA

AGENCY: Federal Aviation Administration (FAA), DOT.