

this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Airbus, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France.

(3) You may review copies at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

TABLE 2.—MATERIAL INCORPORATED BY REFERENCE

Airbus Service Bulletin	Date
A330-53-3161	April 14, 2006.
A330-53-3162	April 6, 2006.
A340-53-4166	April 6, 2006.
A340-53-4167	April 6, 2006.

Issued in Renton, Washington, on February 20, 2008.

Ali Bahrami,

Manager, Transport Airplane Directorate,
Aircraft Certification Service.

[FR Doc. E8-3813 Filed 3-3-08; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2007-0182; Directorate Identifier 2007-NM-138-AD; Amendment 39-15401; AD 2008-05-07]

RIN 2120-AA64

Airworthiness Directives; Dassault Model Fan Jet Falcon, Fan Jet Falcon Series C, D, E, F, and G Airplanes; Model Mystere-Falcon 200 Airplanes; and Model Mystere-Falcon 20-C5, 20-D5, 20-E5, and 20-F5 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for the products listed above. This AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

One occurrence has been reported where a maintenance operation had been performed on the elevator controls, and bellcrank * * *

located in the Right Hand MLG (main landing gear) wheel well was mistakenly installed upside down. This discrepancy and improper installation caused an unexpected 5° positioning offset of the elevator control surfaces leading to a hazardous condition on landing, [involving] the pilot being unable to flare the aircraft as needed * * * [which resulted in a hard landing].

The unsafe condition is reduced controllability of the airplane. We are issuing this AD to require actions to correct the unsafe condition on these products.

DATES: This AD becomes effective April 8, 2008.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of April 8, 2008.

ADDRESSES: You may examine the AD docket on the Internet at <http://www.regulations.gov> or in person at the U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC.

FOR FURTHER INFORMATION CONTACT: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1137; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. That NPRM was published in the **Federal Register** on November 13, 2007 (72 FR 63829). That NPRM proposed to correct an unsafe condition for the specified products. The MCAI states:

One occurrence has been reported where a maintenance operation had been performed on the elevator controls, and bellcrank P/N (part number) MY20273017 or P/N MY20273017015 located in the Right Hand MLG (main landing gear) wheel well was mistakenly installed upside down. This discrepancy and improper installation caused an unexpected 5° positioning offset of the elevator control surfaces leading to a hazardous condition on landing, [involving] the pilot being unable to flare the aircraft as needed * * * [which resulted in a hard landing].

The purpose of this AD is to prevent reoccurrence of this kind of incident introducing disabusing markings on the incriminated parts by applying SB (Service Bulletin) F20-768 or SB F200-122 as appropriate.

The unsafe condition is reduced controllability of the airplane.

Corrective actions include verifying the correct assembly of the elevator bellcrank and re-installing if necessary. You may obtain further information by examining the MCAI in the AD docket.

Comments

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM or on the determination of the cost to the public.

Conclusion

We reviewed the available data and determined that air safety and the public interest require adopting the AD as proposed.

Differences Between This AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have required different actions in this AD from those in the MCAI in order to follow our FAA policies. Any such differences are highlighted in a NOTE within the AD.

Costs of Compliance

We estimate that this AD will affect about 255 products of U.S. registry. We also estimate that it will take about 3 work-hours per product to comply with the basic requirements of this AD. The average labor rate is \$80 per work-hour. Required parts will cost about \$9 per product. Where the service information lists required parts costs that are covered under warranty, we have assumed that there will be no charge for these parts. As we do not control warranty coverage for affected parties, some parties may incur costs higher than estimated here. Based on these figures, we estimate the cost of this AD to the U.S. operators to be \$63,495, or \$249 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII,

Part A, Subpart III, Section 44701: General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

1. Is not a “significant regulatory action” under Executive Order 12866;
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains the NPRM, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the ADDRESSES section. Comments will be available in the AD docket shortly after receipt.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new AD:

2008-05-07 Dassault Aviation (Formerly Avions Marcel Dassault-Breguet Aviation (AMD/BA)): Amendment 39-15401. Docket No. FAA-2007-0182; Directorate Identifier 2007-NM-138-AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective April 8, 2008.

Affected ADs

(b) None.

Applicability

(c) This AD applies to all Dassault Model Fan Jet Falcon, Fan Jet Falcon series C, D, E, F, and G airplanes; Model Mystere-Falcon 200 airplanes; and Model Mystere-Falcon 20-C5, 20-D5, 20-E5, and 20-F5 airplanes, all serial numbers, certificated in any category.

Subject

(d) Air Transport Association (ATA) of America Code 27: Flight Controls.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states: One occurrence has been reported where a maintenance operation had been performed on the elevator controls, and bellcrank P/N (part number) MY20273017 or P/N MY20273017015 located in the Right Hand MLG (main landing gear) wheel well was mistakenly installed upside down. This discrepancy and improper installation caused an unexpected 5° positioning offset of the elevator control surfaces leading to a hazardous condition on landing, [involving] the pilot being unable to flare the aircraft as needed * * * [which resulted in a hard landing].

The purpose of this AD is to prevent recurrence of this kind of incident introducing disabusing markings on the incriminated parts by applying SB (Service Bulletin) F20-768 or SB F200-122 as appropriate.

The unsafe condition is reduced controllability of the airplane. Corrective actions include verifying the correct assembly of the elevator bellcrank and re-installing if necessary.

Actions and Compliance

(f) Within 74 months from the effective date of this AD, unless already done, do the following actions.

(1) Verify the correct assembly of the elevator bellcrank P/N (part number) MY20273-17 or P/N MY20273-17-15 at frame 26, as instructed in Dassault Service Bulletin F20-768, dated May 23, 2006; or Dassault Service Bulletin F200-122, dated May 23, 2006; as applicable.

(2) If the elevator bellcrank is found in the reverse orientation, reinstall it prior to next flight in accordance with Dassault Service Bulletin F20-768, dated May 23, 2006; or Dassault Service Bulletin F200-122, dated May 23, 2006; as applicable.

(3) Label the elevator bellcrank as instructed in Dassault Service Bulletin F20-768, dated May 23, 2006; or Dassault Service Bulletin F200-122, dated May 23, 2006; as applicable.

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1137; fax (425) 227-1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI European Aviation Safety Agency Airworthiness Directive 2006-0185, dated July 6, 2006, and Dassault Service Bulletins F20-768 and F200-122, both dated May 23, 2006, for related information.

Material Incorporated by Reference

(i) You must use Dassault Service Bulletin F20-768, dated May 23, 2006; or Dassault Service Bulletin F200-122, dated May 23, 2006; as applicable, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Dassault Falcon Jet, P.O. Box 2000, South Hackensack, New Jersey 07606.

(3) You may review copies at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on February 20, 2008.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-3816 Filed 3-3-08; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2007-0369; Directorate Identifier 2007-NM-258-AD; Amendment 39-15402; AD 2008-05-08]

RIN 2120-AA64

Airworthiness Directives; Dassault Model Mystere-Falcon 50 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for the products listed above. This AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

Some occurrences have been reported where life rafts were difficult to remove from inside divan compartment. Investigations revealed that:

- Life raft was incorrectly stowed, with deployment straps inboard;
- Life raft had not been repacked to specified dimensions

* * * * *

We are issuing this AD to require actions to correct the unsafe condition on these products.

DATES: This AD becomes effective April 8, 2008.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of April 8, 2008.

ADDRESSES: You may examine the AD docket on the Internet at <http://www.regulations.gov> or in person at the U.S. Department of Transportation,

Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC.

FOR FURTHER INFORMATION CONTACT: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1137; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. That NPRM was published in the **Federal Register** on December 20, 2007 (72 FR 72273). That NPRM proposed to correct an unsafe condition for the specified products. The MCAI states:

Some occurrences have been reported where life rafts were difficult to remove from inside divan compartment. Investigations revealed that:

- Life raft was incorrectly stowed, with deployment straps inboard;
- Life raft had not been repacked to specified dimensions

The purpose of this Airworthiness Directive (AD) is to verify that all life rafts are stowed correctly with deployment straps outboard, and are repacked to specified dimensions.

Corrective actions include correctly reinstalling an incorrectly stowed life raft, installing a properly repacked life raft, and installing placards. You may obtain further information by examining the MCAI in the AD docket.

Comments

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM or on the determination of the cost to the public.

Conclusion

We reviewed the available data and determined that air safety and the public interest require adopting the AD as proposed.

Differences Between This AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have required different actions in this AD from those in the MCAI in order to follow our FAA policies. Any such differences are highlighted in a NOTE within the AD.

Costs of Compliance

We estimate that this AD will affect about 25 products of U.S. registry. We also estimate that it will take about 1 work-hour per product to comply with the basic requirements of this AD. The average labor rate is \$80 per work-hour. Required parts will cost about \$68 per product. Where the service information lists required parts costs that are covered under warranty, we have assumed that there will be no charge for these parts. As we do not control warranty coverage for affected parties, some parties may incur costs higher than estimated here. Based on these figures, we estimate the cost of this AD to the U.S. operators to be \$3,700, or \$148 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and