

---

# Corrections

Federal Register

Vol. 71, No. 73

Monday, April 17, 2006

---

This section of the FEDERAL REGISTER contains editorial corrections of previously published Presidential, Rule, Proposed Rule, and Notice documents. These corrections are prepared by the Office of the Federal Register. Agency prepared corrections are issued as signed documents and appear in the appropriate document categories elsewhere in the issue.

---

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2006-23649; Directorate Identifier 2006-CE-08-AD; Amendment 39-14542; AD 2006-07-15]

RIN 2120-AA64

#### **Airworthiness Directives; Thrush Aircraft, Inc. Model 600 S2D and S2R (S-2R) Series Airplanes**

##### *Correction*

In rule document 06-3162 beginning on page 16691 in the issue of Tuesday,

April 4, 2006, make the following correction:

#### **§ 39.13 [Corrected]**

On page 16694, in § 39.13, in Table 3, under “(iii) *Eddy Current inspection*”, in the second column, “350 hours TIS” should be moved to the third column.

[FR Doc. C6-3162 Filed 4-14-06; 8:45 am]

BILLING CODE 1505-01-D