

effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To ensure the integrity of the fail safe features of the thrust reverser system by preventing possible failure modes in the thrust reverser control system that can result in inadvertent deployment of a thrust reverser during flight, accomplish the following:

Restatement of Requirements of AD 95-06-01

(a) Within 90 days after April 13, 1995 (the effective date AD 95-06-01, amendment 39-9171), perform tests of the position switch module and the cone brake of the center drive unit (CDU) on each thrust reverser, and perform an inspection to detect damage to the bullnose seal on the translating sleeve on each thrust reverser, in accordance with paragraphs III.A. through III.C. of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-78A2130, dated May 26, 1994. Repeat the tests and inspection thereafter at intervals not to exceed 1,000 hours time-in-service until the functional test required by paragraph (d) of this AD is accomplished.

(b) Within 9 months after April 13, 1995, perform inspections and functional tests of the thrust reverser control and indication system in accordance with paragraphs III.D. through III.F., III.H., and III.I. of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-78A2130, dated May 26, 1994. Repeat these inspections and functional tests thereafter at intervals not to exceed 18 months.

(c) If any of the inspections and/or functional tests required by paragraphs (a) and (b) of this AD cannot be successfully performed, or if any discrepancy is found during those inspections and/or functional tests, accomplish either paragraph (c)(1) or (c)(2) of this AD.

(1) Prior to further flight, correct the discrepancy found, in accordance with Boeing Alert Service Bulletin 747-78A2130, dated May 26, 1994. Or

(2) The airplane may be operated in accordance with the provisions and limitations specified in an operator's FAA-approved Minimum Equipment List (MEL), provided that no more than one thrust reverser on the airplane is inoperative.

New Requirements of This AD

(d) Within 1,000 hours time-in-service after the most recent test of the CDU cone brake performed in accordance with paragraph (a) of this AD, or within 650 hours time-in-service after the effective date of this AD, whichever occurs first: Perform a functional test to detect discrepancies of the CDU cone brake on each thrust reverser, in accordance with Boeing Service Bulletin 747-78A2166, Revision 1, dated October 9, 1997, or paragraph III.B. of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-78A2130, dated May 26, 1994. Repeat the functional test thereafter at intervals not

to exceed 650 hours time-in-service. Accomplishment of such functional test constitutes terminating action for the repetitive test of the CDU cone brake required by paragraph (a) of this AD.

(e) If any functional test required by paragraph (d) of this AD cannot be successfully performed, or if any discrepancy is found during any functional test required by paragraph (d) of this AD, accomplish either paragraph (e)(1) or (e)(2) of this AD.

(1) Prior to further flight, correct the discrepancy found, in accordance with Boeing Service Bulletin 747-78A2166, Revision 1, dated October 9, 1997, or paragraph III.B. of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-78A2130, dated May 26, 1994. Or

(2) The airplane may be operated in accordance with the provisions and limitations specified in the operator's FAA-approved MEL, provided that no more than one thrust reverser on the airplane is inoperative.

(f) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

(g) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on January 14, 1999.

Darrell M. Pederson,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 99-1307 Filed 1-20-99; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Airspace Docket No. 98-AGL-80]

Proposed Modification of Class E Airspace; Shelbyville, IN

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking.

SUMMARY: This notice proposes to modify Class E airspace at Shelbyville, IN. A Global Positioning System (GPS) Standard Instrument Approach Procedure (SIAP) to Runway (Rwy) 01, and a GPS SIAP to Rwy 19, have been

developed for Shelbyville Municipal Airport. Controlled airspace extending upward from 700 to 1200 feet above ground level (AGL) is needed to contain aircraft executing the approaches. This action proposes to modify the existing surface area by increasing the radius of the existing controlled airspace for this airport.

DATES: Comments must be received on or before March 3, 1999.

ADDRESSES: Send comments on the proposal in triplicate to: Federal Aviation Administration, Office of the Assistant Chief Counsel, AGL-7, Rules Docket No. 98-AGL-80, 2300 East Devon Avenue, Des Plaines, Illinois 60018.

The official docket may be examined in the Office of the Assistant Chief Counsel, Federal Aviation Administration, 2300 East Devon Avenue, Des Plaines, Illinois. An informal docket may also be examined during normal business hours at the Air Traffic Division, Airspace Branch, Federal Aviation Administration, 2300 East Devon Avenue, Des Plaines, Illinois.

FOR FURTHER INFORMATION CONTACT: Michelle M. Behm, Air Traffic Division, Airspace Branch, AGL-520, Federal Aviation Administration, 2300 East Devon Avenue, Des Plaines, Illinois 60018, telephone (847) 294-7568.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal.

Communications should identify the airspace docket number and be submitted in triplicate to the address listed above. Commenters wishing the FAA to acknowledge receipt of their comments on this notice must submit with those comments a self-addressed, stamped postcard on which the following statement is made:

"Comments to Airspace Docket No. 98-AGL-80." The postcard will be date/time stamped and returned to the commenter. All communications received on or before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained

in this notice may be changed in light of comments received. All comments submitted will be available for examination in the Rules Docket, FAA, Great Lakes Region, Office of the Assistant Chief Counsel, 2300 East Devon Avenue, Des Plaines, Illinois, both before and after the closing date for comments. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

Availability of NPRM's

Any person may obtain a copy of this Notice of Proposed Rulemaking (NPRM) by submitting a request to the Federal Aviation Administration, Office of Public Affairs, Attention: Public Inquiry Center, APA-230, 800 Independence Avenue, S.W., Washington, DC 20591, or by calling (202) 267-3484. Communications must identify the notice number of this NPRM. Persons interested in being placed on a mailing list for future NPRM's should also request a copy of Advisory Circular No. 11-2A, which describes the application procedure.

The Proposal

The FAA is considering an amendment to 14 CFR part 71 to modify Class E airspace at Shelbyville, IN, to accommodate aircraft executing the proposed GPS Rwy 01 SIAP, and the GPS Rwy 19 SIAP, at Shelbyville Municipal Airport by modifying the existing controlled airspace. Controlled airspace extending upward from 700 to 1200 feet AGL is needed to contain aircraft executing the approaches. The area would be depicted on appropriate aeronautical charts. Class E airspace designations for airspace areas extending upward from 700 feet or more above the surface of the earth are published in paragraph 6005 of FAA Order 7400.9E dated September 10, 1998, and effective September 16, 1998, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designation listed in this document would be published subsequently in the Order.

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Therefore, this proposed regulation—(1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated

impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this proposed rule will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me, the Federal Aviation Administration proposes to amend 14 CFR part 71 as follows:

PART 71—DESIGNATION OF CLASS A, CLASS B, CLASS C, CLASS D, AND CLASS E AIRSPACE AREAS; AIRWAYS; ROUTES; AND REPORTING POINTS

1. The authority citation for part 71 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389.

§ 71.1 [Amended]

2. The incorporation by reference in 14 CFR 71.1 of the Federal Aviation Administration Order 7400.9E, Airspace Designations and Reporting Points, dated September 10, 1998, and effective September 16, 1998, is amended as follows:

* * * * *

Paragraph 6005 Class E airspace areas extending upward from 700 feet or more above the surface of the earth.

* * * * *

AGL IN E5 Shelbyville, IN [Revised]

Shelbyville Municipal Airport, IN,
(Lat. 39°34'41" N., long. 85°48'12" W.)
Shelbyville VORTAC,
(Lat. 39°37'57" N., long. 85°49'28" W.)

That airspace extending upward from 700 feet above the surface within a 6.7-mile radius of the Shelbyville Municipal Airport and within 1.8 miles each side of the Shelbyville VORTAC 340° radial extending from the 6.7-mile radius to 9.6 miles north of the VORTAC, excluding the airspace within the Mount Comfort, IN, Class E airspace area.

* * * * *

Issued in Des Plaines, Illinois on December 31, 1998.

Michelle M. Behm,

Acting Manager, Air Traffic Division.

[FR Doc. 99-1100 Filed 1-20-99; 8:45 am]

BILLING CODE 4910-13-M

DEPARTMENT OF TRANSPORTATION

Office of the Secretary

14 CFR Part 389

[Docket No. OST-99-5003; Notice No. 99-1]

RIN 2105-AC47

Fees and Charges for Special Services

AGENCY: Office of the Secretary, DOT.

ACTION: Notice of proposed rulemaking.

SUMMARY: The Department is proposing to revise 14 CFR Part 389 to bring the fees we charge to beneficiaries of certain economic, aviation-related licensing services in line with the costs incurred to provide those services. We also are proposing to remove or update obsolete provisions and organizational references included in the existing regulations.

DATES: Comments should be received no later than March 22, 1999.

ADDRESSES: Five (5) copies of any comments should be sent to Department of Transportation Dockets, Room PL-401, 400 7th Street, SW., Washington, DC 20590-0002, and should refer to this docket. Acknowledgment of comments requires you to include a stamped, self-addressed postcard that the Docket clerk will time and date-stamp, and return.

FOR FURTHER INFORMATION CONTACT: Mr. James H. New or Mr. John D. Miller, Office of Planning and Special Projects, X-60, Department of Transportation, at the address above. Telephone (202) 366-4868.

SUPPLEMENTARY INFORMATION: Part 389 of Title 14 of the Code of Federal Regulations—Fees and Charges for Special Services—describes certain special services related to aviation economic proceedings that the Department provides to the public, and sets forth the fees and charges applicable to those services. This regulation has not been comprehensively updated since January 1983, when economic regulation of interstate and foreign air transportation was overseen by the Civil Aeronautics Board. Congress "sunset" the Board in January 1985, at which time the Board's residual functions were transferred to the Office of the Secretary, DOT. Today, some of the services identified in Part 389 are no longer provided, while several other services are provided but are not included. Further, most of the service processing fees prescribed in section 389.25(a) are not sufficient to recover our processing costs, while the prescribed fee in a few instances is too high. Because of these conditions, the General Accounting Office has