

having outboard spoiler actuator brackets with part numbers 85714052–101 or 85714052–102.

**(d) Subject**

Air Transport Association (ATA) of America Code 57, Wings.

**(e) Reason**

This AD was prompted by a report of a cracked outboard spoiler actuator mounting bracket. We are issuing this AD to address cracking of the outboard spoiler actuator mounting brackets, which could cause inoperability or jam of a single spoiler panel and possible jam of the aileron circuit. This condition, if not corrected, could adversely affect the continued safe operation and landing of the airplane.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Repetitive Inspections**

At the applicable time specified in paragraph (g)(1) or (g)(2) of this AD: Do a general visual inspection for cracks in the left and right outboard spoiler actuator mounting brackets having part number (P/N) 85714052–101 or 85714052–102 (belonging to assemblies having P/N 85714018–001 or P/N 85714018–002, respectively), in accordance with Section 3.B, Part A, of the Accomplishment Instructions of Bombardier Service Bulletin 84–27–72, Revision A, dated November 9, 2017. Repeat the inspection thereafter at intervals not to exceed 8,000 flight hours.

(1) For airplanes having less than 12,000 total flight hours as of the effective date of this AD: Prior to the accumulation of 18,000 total flight hours.

(2) For airplanes having 12,000 total flight hours or more as of the effective date of this AD: Within 6,000 flight hours after the effective date of this AD.

**(h) Part Replacement**

(1) If, during any inspection required by paragraph (g) of this AD, either the left or right outboard spoiler actuator mounting bracket is found cracked: Before further flight, replace both the left and right brackets with new bracket assemblies having P/N 85714018–003 or P/N 85714018–004, including doing all applicable related investigative actions and corrective actions, in accordance with Section 3.B, Part B, of the Accomplishment Instructions of Bombardier Service Bulletin 84–27–72, Revision A, dated November 9, 2017; except, where the service information specifies contacting Bombardier for corrective action, this AD requires accomplishing the action using a method approved by the Manager, New York ACO Branch, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(2) If, during any inspection required by paragraph (g) of this AD, no cracking is found on the left and right outboard spoiler actuator mounting brackets, and the left and right outboard spoiler actuator mounting brackets

have not already been replaced per the requirements of paragraph (h)(1) of this AD: Replace both the left and right brackets with new bracket assemblies having P/N 85714018–003 or P/N 85714018–004, including doing all applicable related investigative actions and corrective actions, at the applicable time specified in paragraph (h)(2)(i) or (h)(2)(ii) of this AD, in accordance with Section 3.B, Part B, of the Accomplishment Instructions of Bombardier Service Bulletin 84–27–72, Revision A, dated November 9, 2017; except, where the service information specifies contacting Bombardier for corrective action, this AD requires accomplishing the action using a method approved by the Manager, New York ACO Branch, FAA; or TCCA; or Bombardier, Inc.'s TCCA DAO. If approved by the DAO, the approval must include the DAO-authorized signature. Related investigative and corrective actions must be done before further flight.

(i) For airplanes that have accumulated less than 34,000 total flight hours as of the effective date of this AD: Replace the outboard spoiler actuator mounting brackets prior to the airplane accumulating 40,000 total flight hours.

(ii) For airplanes that have accumulated 34,000 total flight hours or more as of the effective date of this AD: Replace the outboard spoiler actuator mounting brackets within 6,000 flight hours after the effective date of this AD.

**(i) Terminating Action for Repetitive Inspections**

Replacement of an outboard spoiler actuator mounting bracket, in accordance with the requirements of paragraph (h) of this AD, is terminating action for the repetitive inspections required by paragraph (g) of this AD for the replaced bracket.

**(j) Credit for Previous Actions**

This paragraph provides credit for the actions required by paragraphs (g) and (h) of this AD, if those actions were performed before the effective date of this AD using Bombardier Service Bulletin 84–27–72, dated January 19, 2017.

**(k) Other FAA AD Provisions**

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7300; fax 516–794–5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; or TCCA; or Bombardier, Inc.'s TCCA DAO. If approved by the DAO, the approval must include the DAO-authorized signature.

**(l) Related Information**

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian AD CF–2018–21R1, effective November 1, 2018, for related information. This MCAI may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2019–0120.

(2) For more information about this AD, contact Kristopher Greer, Aerospace Engineer, Aviation Safety Section AIR–7B1, Boston ACO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; telephone 781–238–7799.

(3) For information about AMOCs, contact Aziz Ahmed, Aerospace Engineer, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, New York 11590; telephone: 516–287–7329; fax: 516–794–5531; email: [Aziz.Ahmed@faa.gov](mailto:Aziz.Ahmed@faa.gov).

(4) For service information identified in this AD, contact Bombardier, Inc., Q-Series Technical Help Desk, 123 Garratt Boulevard, Toronto, Ontario M3K 1Y5, Canada; telephone 416–375–4000; fax 416–375–4539; email [thd.qseries@aero.bombardier.com](mailto:thd.qseries@aero.bombardier.com); internet <http://www.bombardier.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

Issued in Des Moines, Washington, on March 13, 2019.

**Dionne Palermo,**

*Acting Director, System Oversight Division, Aircraft Certification Service.*

[FR Doc. 2019–05209 Filed 3–20–19; 8:45 am]

**BILLING CODE 4910–13–P**

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 71**

**[Docket No. FAA–2019–0140; Airspace Docket No. 19–ASO–3]**

**RIN 2120–AA66**

**Proposed Amendment of Class E Airspace, Fort Payne, AL**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This action proposes to amend Class E airspace extending upward from 700 feet above the surface in Isbell Field Airport, Fort Payne, AL,

to accommodate airspace reconfiguration due to the decommissioning of the Fort Payne non-directional radio beacon and cancellation of the NDB approach. Controlled airspace is necessary for the safety and management of instrument flight rules (IFR) operations at this airport. This action also would update the airport name and geographic coordinates of this airport. In addition, this action would update the name and geographic coordinates of Dekalb Regional Medical Center Heliport, which is contained within the legal description of the Isbell Field Airport airspace.

**DATES:** Comments must be received on or before May 6, 2019.

**ADDRESSES:** Send comments on this proposal to: the U.S. Department of Transportation, Docket Operations, 1200 New Jersey Avenue SE, West Building Ground Floor, Room W12-140, Washington, DC 20590-0001; Telephone: (800) 647-5527, or (202) 366-9826. You must identify the Docket No. FAA-2019-0140; Airspace Docket No. 19-ASO-3, at the beginning of your comments. You may also submit comments through the internet at <http://www.regulations.gov>.

FAA Order 7400.11C, Airspace Designations and Reporting Points, and subsequent amendments can be viewed on line at [http://www.faa.gov/air\\_traffic/publications/](http://www.faa.gov/air_traffic/publications/). For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC, 20591; telephone: (202) 267-8783. The Order is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of FAA Order 7400.11C at NARA, call (202) 741-6030, or go to <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

FAA Order 7400.11, Airspace Designations and Reporting Points, is published yearly and effective on September 15.

**FOR FURTHER INFORMATION CONTACT:** John Fornito, Operations Support Group, Eastern Service Center, Federal Aviation Administration, 1701 Columbia Avenue, College Park, GA 30337; telephone (404) 305-6364.

#### **SUPPLEMENTARY INFORMATION:**

##### **Authority for This Rulemaking**

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator.

Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace.

This regulation is within the scope of that authority as it would amend Class E airspace at Isbell Field Airport, and Dekalb Regional Medical Center Heliport, Fort Payne, AL to support IFR operations in the area.

##### **Comments Invited**

Interested persons are invited to comment on this proposed rulemaking by submitting such written data, views, or arguments, as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal.

Communications should identify both docket numbers (Docket No. FAA-2019-0140 and Airspace Docket No. 19-ASO-3) and be submitted in triplicate to DOT Docket Operations (see **ADDRESSES** section for the address and phone number). You may also submit comments through the internet at <http://www.regulations.gov>.

Persons wishing the FAA to acknowledge receipt of their comments on this action must submit with those comments a self-addressed stamped postcard on which the following statement is made: "Comments to FAA Docket No. FAA-2019-0140; Airspace Docket No. 19-ASO-3." The postcard will be date/time stamped and returned to the commenter.

All communications received before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this document may be changed in light of the comments received. All comments submitted will be available for examination in the public docket both before and after the comment closing date. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

##### **Availability of NPRMs**

An electronic copy of this document may be downloaded through the

internet at <http://www.regulations.gov>. Recently published rulemaking documents can also be accessed through the FAA's web page at [http://www.faa.gov/air\\_traffic/publications/airspace\\_amendments/](http://www.faa.gov/air_traffic/publications/airspace_amendments/).

You may review the public docket containing the proposal, any comments received and any final disposition in person in the Dockets Office (see the **ADDRESSES** section for address and phone number) between 9:00 a.m. and 5:00 p.m., Monday through Friday, except federal holidays. An informal docket may also be examined between 8:00 a.m. and 4:30 p.m., Monday through Friday, except federal holidays at the office of the Eastern Service Center, Federal Aviation Administration, Room 350, 1701 Columbia Avenue, College Park, GA 30337.

##### **Availability and Summary of Documents for Incorporation by Reference**

This document proposes to amend FAA Order 7400.11C, Airspace Designations and Reporting Points, dated August 13, 2018, and effective September 15, 2018. FAA Order 7400.11C is publicly available as listed in the **ADDRESSES** section of this document. FAA Order 7400.11C lists Class A, B, C, D, and E airspace areas, air traffic service routes, and reporting points.

##### **The Proposal**

The FAA proposes an amendment to Title 14 Code of Federal Regulations (14 CFR) part 71 to amend Class E airspace extending upward from 700 feet or more above the surface at Isbell Field Airport, Fort Payne, AL, by increasing the airport radius to 10.6 miles (from 7.4 miles), eliminating the northwest extension of the airport, and creating a 13.5-mile extension southwest of the airport, to accommodate airspace reconfiguration due to the decommissioning of the Fort Payne NDB and cancellation of the NDB approach. This action would also remove the city name below the description header, to comply with FAA Order 7400.2M, Procedures for Handling Airspace Matters; removing the city associated with the airport from the airspace legal description.

The airspace redesign would enhance the safety and management of IFR operations at the airport. The geographic coordinates of the airport would be adjusted to coincide with the FAA's aeronautical database. Also, the name and geographic coordinates of Dekalb Regional Medical Center Heliport, (formerly Dekalb Medical Center) would

be updated to coincide with the FAA's aeronautical database.

Class E airspace designations are published in Paragraph 6005 of FAA Order 7400.11C, dated August 13, 2018, and effective September 15, 2018, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designation listed in this document will be published subsequently in the Order.

### Regulatory Notices and Analyses

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore: (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this proposed rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

### Environmental Review

This proposal will be subject to an environmental analysis in accordance with FAA Order 1050.1F, "Environmental Impacts: Policies and Procedures" prior to any FAA final regulatory action.

### Lists of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

### The Proposed Amendment

In consideration of the foregoing, the Federal Aviation Administration proposes to amend 14 CFR part 71 as follows:

### PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

■ 1. The authority citation for part 71 continues to read as follows:

**Authority:** 49 U.S.C. 106(f), 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

#### § 71.1 [Amended]

■ 2. The incorporation by reference in 14 CFR 71.1 of Federal Aviation Administration Order 7400.11C, Airspace Designations and Reporting Points, dated August 13, 2018, and

effective September 15, 2018, is amended as follows:

*Paragraph 6005 Class E Airspace Areas Extending Upward From 700 Feet or More Above the Surface of the Earth.*

\* \* \* \* \*

#### ASO AL E5 Fort Payne, AL [Amended]

Isbell Field Airport, AL

(Lat. 34°28'25" N, long. 85°43'17" W)

Dekalb Regional Medical Center Heliport, AL

(Lat. 34°26'32" N, long. 85°45'21" W)

That airspace extending upward from 700 feet above the surface within a 10.6-mile radius of the Isbell Field Airport, and within 4 miles each side of the 220° bearing from the airport, extending from the 10.6-mile radius to 13.6 miles southwest of the airport, and that airspace within a 6-mile radius of Dekalb Regional Medical Center Heliport.

Issued in College Park, Georgia, on March 8, 2019.

**Ryan W. Almasy,**

*Manager, Operations Support Group, Eastern Service Center, Air Traffic Organization.*

[FR Doc. 2019-04787 Filed 3-20-19; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 71

[Docket No. FAA-2019-0110; Airspace Docket No. 19-ASW-3]

**RIN 2120-AA66**

### Proposed Amendment of the Class D and Class E Airspace; Tulsa, OK

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This action proposes to amend the Class D airspace and Class E airspace extending upward from 700 feet above the surface at Richard Lloyd Jones Jr. Airport, Tulsa, OK, and the Class E airspace extending upward from 700 feet above the surface at William R. Pogue Municipal Airport, Sand Springs, OK, which is contained within the Tulsa, OK, airspace legal description. The FAA is proposing this action as the result of the decommissioning of the Glenpool VHF omnidirectional range (VOR) navigation aid, which provided navigation information for the instrument procedures at these airports, as part of the VOR Minimum Operational Network (MON) Program. The geographic coordinates of the Richard Lloyd Jones Jr. Airport would also be updated to coincide with the FAA's aeronautical database.

**DATES:** Comments must be received on or before May 6, 2019.

**ADDRESSES:** Send comments on this proposal to the U.S. Department of Transportation, Docket Operations, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590; telephone (202) 366-9826, or (800) 647-5527. You must identify FAA Docket No. FAA-2019-0110; Airspace Docket No. 19-ASW-3, at the beginning of your comments. You may also submit comments through the internet at <http://www.regulations.gov>. You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office between 9:00 a.m. and 5:00 p.m., Monday through Friday, except federal holidays.

FAA Order 7400.11C, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at [http://www.faa.gov/air\\_traffic/publications/](http://www.faa.gov/air_traffic/publications/). For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267-8783. The Order is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of FAA Order 7400.11C at NARA, call (202) 741-6030, or go to <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

FAA Order 7400.11, Airspace Designations and Reporting Points, is published yearly and effective on September 15.

#### FOR FURTHER INFORMATION CONTACT:

Jeffrey Claypool, Federal Aviation Administration, Operations Support Group, Central Service Center, 10101 Hillwood Parkway, Fort Worth, TX 76177; telephone (817) 222-5711.

#### SUPPLEMENTARY INFORMATION:

#### Authority for This Rulemaking

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it would